

# Wind Tunnel Level 1 Certification

To gain level 1 certification for the wind tunnel, you must complete these steps:

- i. Watch the basic safety video for the flow lab (Available on the Endeavor website)
- ii. Watch the Aerolab's Aeroware program video (Available on the Endeavor website)
- iii. Take the D21 safety quiz (required 100% to pass with 3 attempts max)
- iv. Print off the webpage showing that you got a 100%, must show your name on the printout
- v. Write your CWID and email on the printed page
- vi. Take the printed page to ENDV 225 and get your white Endeavor safety card hole punched

Completing this process will result in access to the wind tunnel while being **supervised** by a TA/level 4 certified individual.

\*\*\*Hours to be supervised can be scheduled by emailing a TA/level 4 certified individual. However, level 1 certification is primarily for students taking a class that involves use of the wind tunnel while under TA supervision. It is highly recommended for every student to at least gain a level 2 certification for the wind tunnel.

If you need further help, contact information for those that are available to help will be under the Wind Tunnel tab as well.